B.G. MICRO P.O. Box 280298 Dallas, Texas 75228 (214) 271-5546

Dear Customer,

Some of the Xerox Boards were manufactured with a nickel plating rather than tin-lead. These can be identified by an x in a circle next to the part # on the foil side of the board. These nickel boards require more heat when soldering and will take a little more time to assemble. Take your time!

Caution:

If you use a soldering aid of any kind, be sure and clean board thoroughly when complete.

Best Regards,

Billy Gage

Billy Gage
B.G. MICRO

tjm